



BRUNETTE MACHINERY

Cordless Torque Wrench

Available for Rental

For the 4800 Series Grizzly Mill (Models 4836, 4848, 4860, 4872)

The required torque of striker bar bolts is 2000 ft/lbs (wet), 2400 ft/lbs (dry). Some customers expressed concern that this torque will exceed the limitation of most mechanical multipliers.

Brunette Machinery Service offers a cordless torque wrench for rental, with custom slave arm, designed to aid in the removal of striker bars. The torque wrench and slave arm are shown below and are shipped complete with operating instructions. Contact us for rental information.



This torque wrench dramatically reduces the time required to replace a set of striker bars and ensures the bolts are torqued to specification.


Rental units are available from our Surrey and Prince George locations.

Please contact Sonia at **604.522.3977** or email: parts@brunettemc.com



Cordless Torque Wrench Components Included:

- One (1) Cordless torque wrench
- Two (2) 1" Drive Impact Sockets, 2-³/₁₆" & 2-¹/₄"
- One (1) Standard reaction arm
- Two (2) 18V 5.2Ah LILON batteries
- One (1) Hand guard
- One (1) 120V Smart Charger with cord
- One (1) 1" Allen wrench
- One (1) Weather-proof carrying case



Rental units are available from our Surrey & Prince George locations.

Call Sonia: **604.522.3977**, email: parts@brunettemc.com, visit: BrunetteMC.com